

SERVICE BULLETIN



M1274

May 10, 2010

Tool Kit Running Change

Purpose

The purpose of this bulletin is to inform dealers of a running change to the tool kit provided with certain Touring and Trike model vehicles. This change went into effect in early February 2010.

Vehicles Affected

This information applies to all 2010 FLHTC, FLHTCU, FLHTK, FLHX, FLTRX, FLHTCUTG and FLHXXX models.

Markets Affected

All markets are affected.

Required Dealer Action

NOTE

There are no carryover parts in the new tool kit.

See Figure 1. Update appropriate literature and notify the parts and service personnel of running change from Tool Kit (Part No. 94435-02B) to Tool Kit (Part No. 94435-10).




Figure 1. Service Supplement Page

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

©2010 H-D